

ENGINEERING BULLETIN

September 3, 2002

AF1080 Air Filter AF1130 Air Filter

This bulletin is to announce that there has been a change to some applications originally using the AF1080 panel air filter.

Some 1999-2001 Super Duty F Series and 2000-01 Ford Excursions, with the 7.3L DIT engine built before 11/25/00, have been experiencing lack of power, according to a recent Ford bulletin. According to Ford, "This lack of power may be caused by a collapsed air filter or a defective air box/lid". If this problem exists, Ford

has recommended changing the air cleaner assembly and air element on these vehicles.

Because some vehicles have been converted from the original OE housing to a retrofit housing, when changing a filter on these vehicles, you may encounter either of these two filters on any of these 1999-2001 trucks with the 7.3L DIT engine. Please be sure to verify your housing number so the correct filter can be used. All catalogs will be altered to reflect these changes.

	Housing	Motorcraft	Hastings	Height
Original Element	NA	FA1680	AF1080	2 1/4 inches
Retrofit Element	1C3Z-9600-AA	FA1710	AF1130	3 inches

**If you have further questions,
please contact our
Service Engineering Team at (800) 887-8836.**